


NO
THERMOPLASTIC
ROOF LIGHTS



A DETAILED METHOD STATEMENT SHOULD BE PROVIDED BY THE MAINTENANCE COMPANY PRIOR TO CARRYING OUT ANY MAINTENANCE WORKS



Manufacturer - Axitec
Panel reference - AC-250M/156-60S

www.axitecsolar.com



A DETAILED METHOD STATEMENT SHOULD BE PROVIDED BY THE MAINTENANCE COMPANY PRIOR TO CARRYING OUT ANY MAINTENANCE WORKS

Please refer to purlin spacing, double spanning situations according to the load/span table on page 3 of the Kingspan data sheet.



ROOF LOADS

Checked by **NM**
Scale **1:100 @ A1**

Revision:

†: 0191 260 5551

e: admin@projektarchitects.com
www.projektarchitects.com

